



Fig.1a Bath stability tests in APM [min] (1:5:20/1:1:200), 70-75°C,60min. Bis Tris(0.195 w %)

Decomposition of H202 in APM without/with (1:5:20) Bis Tris and decomposition of H202 in APM without/with (1:1:200) Bis Tris



BEST AVAILABLE COPY






Fig.2: Cleaning results with different SC-1 mixtures referring to surface contaminations by Fe, Al, Zn and Ca





Fig.3 Comparison: Fe concentration after SC-1 with/without CA



4/10

Fig.4




Fig.5
Comparison: Zn concentration after SC-1 with/without CA




Fig.6
Comparison: Al concentration after SC-1 with/without CA




Fig.7
Comparison: SC-1 vs.SC-1+dHC1 vs.SC-1+SC-2 vs.SC-1+CA




Fig.8




Fig.9
Comparison: SC-1 [1:1:200] with and without




Fig.10 Decomposition of H_2 O_2 in SC-1 [1:1:200]@ 70-75°C




Fig.11 Decomposition of H_2O_2 in SC-1 [1:5:20]@ 70-75°C





Fig.12



This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

BLACK BORDERS

IMAGE CUT OFF AT TOP, BOTTOM OR SIDES

FADED TEXT OR DRAWING

BLURRED OR ILLEGIBLE TEXT OR DRAWING

SKEWED/SLANTED IMAGES

COLOR OR BLACK AND WHITE PHOTOGRAPHS

GRAY SCALE DOCUMENTS

LINES OR MARKS ON ORIGINAL DOCUMENT

REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY

IMAGES ARE BEST AVAILABLE COPY.

OTHER:

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.